Work Order ID 104894 \*104894\* Page 1 Tuesday, July 23, 2013 9:16:03 AM Accept \*N900040100\* Item ID: D2370-1 Setup Start **Revision ID:** Item Name: Litter Frame Assembly **Start Date:** 7/23/2013 Start Oty: 4.00 **Cust Item ID:** Required Date: 7/26/2013 Req'd Qty: 4.00 **Customer:** Reference: Run Date: 131727 Tooling: Process Plan: WWF **Approvals:** Date: QC: SPC (Y/N): Date: Date: Sequence ID/ Operation Tool ID Tool# Plan Reject Reject Set Up/ Accept Number Stamp Work Center ID **Description Qty Run Hours** Code Draw Nbr Revision, Nbr D2370 100 0.00 **PURCHASING** objective to 2078 \*100\* Purchasing 0.00 Memo Purchasing issue p/o: Order: Model 12-2A undrilled with grev pad & black belts Supplier: Ferno Aviation Letter of compliance required 110 Receive & Inspect for Damage & Mat'l Certs 0.00 \*110\* 0.00 Packaging Memo Insure that letter of compliance is attached to w/o Packaging QC6- Inspect dimensions to drawing 0.00 120 \*120\* 0.00 QC, Memo Quality Control



NCR:	Yes	/	No

## WORK ORDER NON-CONFORMANCE / UPDATE

DQA:	Date:	
	<del></del>	

NCN.	163	7 110							VIANCE / OI		QA Closed:	Dat	te:	
Work Orde	er:					DISPOSITION				AGAINST DE	PARTMENT	/PROCESS		
Part N	-				·····	Rework Scrap		Skid-tube Crosstube  Machining Small Fab			Water Jet Prod. Eng. Coor.		Engineering Quality	
NCR N	No.		<del> </del>			Use-as-is Work Order Update				Finishing Composite				
Root					Descri	ption of work order update	Ir	nitial	Ac	tion	Sign &		ŀ	
Cause		Date	Step	Qty	(	or Non-conformance	Chi	ef Eng	Desc	cription	Date	Verification	n QC Inspec	tor
Doc/Data						•								
Equip/Tooling														
Operator														
Material		i			1									
Setup												ı		
Other														
Process							1							
Supplier														
Training				, .										
Unapproved														
						F.	AUL'	T CATE	GORY					
Landi	ng G	Gear				General	_				_	,		
	Ш	Bending				Bend	Ш	Grain			Ovalized		Pressure/Force	
	Ш	Centre No	ot Concer	ntric to	o/s	_BOM/Route	Ш	Hardwa	re		Over/Under	tolerance	Temperature/0	Cure
	Ш	Cracks				Broken/Damaged	Ц	Inspect	ion Incomplete		Part Incorre	ct	Weld	
	Ш	Crushed/0	Crimped			Burrs	Ш	Instruct	ions Incomplete/	/Unclear	Part Lost/Mi	ssing	Wrong Stock P	ulied
	Cuffs					Contamination	Ц	Mainte	enance		Part Moved			
		Heat Trea	it			Countersink	Ш	Mislabe	eled		Positioned V			
	Inspection Strip in Tube					Cut Too Short	Ш	Misread	t		Power Loss/	Surge	Other	
		Ripples in	Bend			Drill Holes	Ш	Offset						
		Torque W	aves in E	Extrusio	n _	Drawing	Ш	Out of	Calibration					
	Turning Sequence Finish					Finish		Out of	Sequence					
1	Wave/Twist in Tube						17	Outcide	Dimonsions					

Packaging

											DQA:	Date:	
NCR: Y	es / No	1			WORK C	ORDER NON-	CON	FORN	MANCE / UP	PDATE			
									<u> </u>		QA Closed:	Date:	
Work Orde	r:				DI	SPOSITION				AGAINST D	EPARTMENT,	/PROCESS	
Part N						Rework Scrap		Skid-tube Crosstube Machining Small Fab			Pro	Water Jet d. Eng. Coor	Engineering Quality
NCR N	lo				Work	Use-as-is Thermoforming Finishing Work Order Update Large Fab Composite			Rec/Sto	Other			
Root				Desci	ription of wor	k order update	ln	nitial	Ad	ction	Sign &		
Cause	Date	Step	Qty	•	or Non-confo	ormance	Chie	ef Eng	Desc	cription	Date	Verification	QC Inspector
Ooc/Data quip/Tooling Operator Material													
etup													
Other	$\dashv$	1											
rocess													
Supplier													
raining							1					ļ	
Jnapproved													
n						F	AULT	CATE	GORY				·
Landir	ng Gear			_	_	eneral	_			_		_	,
	Bendin	•			Bend		$\mathbf{H}$	Grain		-	Ovalized	<u> </u>	Pressure/Forced
		Not Conce	entric to	o/s	BOM/Route		$\vdash$	Hardwa		-	Over/Under		Temperature/Cure
	Cracks		•	-	Broken/Dai	maged	-	•	on Incomplete	,, , <u> </u>	Part Incorre	<del>-</del>	Weld
		d/Crimped	I	-	Burrs		_		ons Incomplete	Junciear	Part Lost/M Part Moved	issing [	Wrong Stock Pulled
	Cuffs				Contaminati Countersin		-	Mainte Mislabe		-	Positioned V	Mrong	
	Heat Treat Inspection Strip in Tube				Cut Too Sho		$\vdash$	Misread		F	Power Loss/		Other
		in Bend	TUDE	 	Drill Holes		$\vdash$	Offset	ı	L			
		Waves in	Extrusio	, F	Drawing		-		Calibration			<del> </del>	
		g Seguence			Finish		$\vdash$		equence				

Outside Dimensions

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Wave/Twist in Tube

Folio

Work Order ID 104894 \*104894\* Page 3 Tuesday, July 23, 2013 9:16:03 AM Item ID: D2370-1 Accept Setup Start \*N900040100\* **Revision ID:** Stop Litter Frame Assembly Item Name: \*4\* Start Qty: 4.00 7/23/2013 **Start Date: Cust Item ID:** Required Date: 7/26/2013 **Req'd Qty:** 4.00 **Customer:** Reference: Run **Tooling:** Process Plan: **Approvals:** Date: Date: Stop QC: SPC (Y/N): Date: Date: Sequence ID/ Set Up/ Tool ID Reject Reject Operation Tool # Plan Accept Insp. **Work Center ID** Qty Qty Number Stamp **Description** Code Run Hours QC21- Final Inspection - Work Order Release 0.00 160 \*160\* MLJ 13-07-26 QC 0.00 Memo Quality Control

			DQA:	Date:	
NCR.	Yes / No	WORK ORDER NON-CONFORMANCE / LIPDATE		_	

NCR:	Yes	/ No	*			WORK ORDER N	ON-CO	NFORM	MANCE / UPDA	TE			
			i								QA Closed:	Date:	
Work Ord	er:					DISPOSITION	l			AGAINST DEI	PARTMENT,	/PROCESS	
Part No.  NCR No.  Root Desc					Sci	<b></b> 1			Small Fab Finishing		Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other	
Root		-			Desci	ription of work order upo	date	Initial	Action		Sign &		
Cause		Date	Step	Qty		or Non-conformance	c	hief Eng	Descripti	ion	Date	Verification	QC Inspector
Doc/Data										_	-		
Equip/Tooling													
Operator										·			
Material			ļ				·						
Setup			}				-						
Other			ļ		İ		İ						
Process			Ì		[	•							
Supplier							-						
Training							İ						
Unapproved													
							FAU	ILT CATE	GORY				
Landi	ing (	Gear				General	,					<u></u>	_
		Bending				Bend	L	Grain			Ovalized		Pressure/Forced
	Centre Not Concentric to O/S					BOM/Route		Hardwa	ire		Over/Under	tolerance	Temperature/Cure
	Cracks					Broken/Damaged		Inspection Incomplete			Part Incorre	ct	Weld
Crushed/Crimped Burrs						Burrs		Instruct	Instructions Incomplete/Unclear			issing	Wrong Stock Pulled

Maintenance

Out of Calibration

Out of Sequence

Outside Dimensions

Mislabeled

Misread

Offset

Contamination

Countersink

Cut Too Short Drill Holes

Drawing

Finish

Folio

Part Moved

Positioned Wrong

Power Loss/Surge

Other

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Cuffs

Heat Treat

Inspection Strip in Tube

Torque Waves in Extrusion

Location Loc Oty Loc Code 80 Mezz 80 16 FF 13-07-24 AN960JD416L NAS1149D0416J Each 4.0000 Purchased 125773 Washer Loc Qty Loc Code Location

110153

FP001

02370-041 x4 102078


Page 1

Status

	NCR: Yes / No					WORK ORDER NON CONFORMANCE / URBATE					DQA	:Date	:	
NCR: Ye	es /	No				WORK ORDER NON-C	ON	NFORM	VIANCE / UP	DATE	QA Closed	: Date	:	
Work Order	:					DISPOSITION AGAINST DI					EPARTMEN <sup>1</sup>	EPARTMENT/PROCESS		
Part No						Rework Scrap Use-as-is Work Order Update		Skid-tube Crosstube  Machining Small Fab  Thermoforming Finishing  Large Fab Composite			Pro Rec/Sto	Engineering Quality Other		
Root					Descrip	otion of work order update	1	Initial	Ac	tion	Sign &			
Cause	D	ate	Step	Qty	o	r Non-conformance	Ch	ief Eng	Desc	ription	Date	Verification	QC Inspecto	
Doc/Data  Equip/Tooling  Operator  Material  Setup  Other						·								

## **FAULT CATEGORY Landing Gear** General Pressure/Forced Bend Grain Ovalized Bending BOM/Route Over/Under tolerance Temperature/Cure Centre Not Concentric to O/S Hardware Broken/Damaged Inspection Incomplete Part Incorrect Weld Cracks Wrong Stock Pulled Crushed/Crimped Burrs Instructions Incomplete/Unclear Part Lost/Missing Cuffs Part Moved Contamination Maintenance Positioned Wrong Mislabeled Heat Treat Countersink Other Misread Power Loss/Surge Inspection Strip in Tube Cut Too Short Drill Holes Offset Ripples in Bend Torque Waves in Extrusion Drawing Out of Calibration Out of Sequence Turning Sequence Finish Folio Outside Dimensions Wave/Twist in Tube

Process
Supplier
Training
Unapproved




NCR: Yes / No	WORK ORDER NON-CON	FORMANCE / UPI	DATE	
			QA	Closed:
Work Order:	DISPOSITION		AGAINST DEPAR	TMENT/PRO
Work Order.	Rework	Skid-tube	Crosstube	W
Part No.	Scrap	Machining	Small Fab	Prod. En

			_								QA Closed:	Date			
Work Orde	er:					DISPOSITION		AGAINST DEPARTMENT/PROCESS							
Part N NCR N						Rework Scrap Use-as-is Work Order Update  Skid-tube Machining Small Fab Thermoforming Large Fab Composite				Pro Rec/Sto	Engineering Quality Other				
Root					Descri	ption of work order update	Ti	nitial	Act	tion	Sign &				
Cause	Di	ate Ste	ep	Qty	(	or Non-conformance	Ch	ief Eng	Desc	ription	Date	Verification	QC Inspector		
Doc/Data				1											
Equip/Tooling		ļ													
Operator															
Material												<u> </u>			
Setup															
Other	Ш			l											
Process															
Supplier			1	1											
Training	H														
Unapproved						_							<u> </u>		
						· · · · · · · · · · · · · · · · · · ·	AUL	T CATE	GORY						
Landi	ng Gear					General		٠:		_	Ovalized	Г	Pressure/Forced		
	Ben	_			,, <u> </u>	Bend BONA (Bounts	$\vdash$	Grain Hardwa		-	Over/Unde	toloranco	Temperature/Cure		
	$\vdash$	tre Not Co	ncent	ric to U	"  -	BOM/Route Broken/Damaged	-	1	ire ion Incomplete	<u> </u>	Part Incorre		Weld		
	Crac	:ks shed/Crim;	20d		-	Burrs	$\vdash$	1	tions Incomplete/	Unclear	Part Lost/M	<u> </u>	Wrong Stock Pulled		
	<b></b>	-	peu		-	Contamination	$\vdash$	Mainte	·	Officieal	Part Moved	_	Twice stock i dired		
}	Cuffs Heat Treat					Countersink	-	Mislabe		-	Positioned				
	Inspection Strip in Tube				<b>—</b>	Cut Too Short	$\vdash$	Misrea			Power Loss	· .	Other		
Ripples in Bend					 	Drill Holes		Offset				- U			
	Torque Waves in Extrusion					Drawing	$\vdash$	4	Calibration		<del>*******</del>				
	Turning Sequence				-	Finish	Out of Sequence								
	Wave/Twist in Tube					Folio		Outside Dimensions							

DQA:

Date:



				DQA:	Date:
NCR.	Vec /	No	WORK ORDER NON-CONFORMANCE / UPDATE		

NCR: Yes /	CR: Yes / No WORK ORDER NON-CONFORMANCE / UPDATE  QA Closed: Date:										
Work Order: Part No NCR No			Rework Skid-tube Crosstube Machining Small Fab Thermoforming Finishing Work Order Update Large Fab Composite					PARTMENT,		Engineering Quality Other	
Root Cause D	ate Step	Qty Descri	ription of work order update or Non-conformance		nitial ef Eng	Action Description		Sign & Date	Verification	QC Inspector	
Doc/Data Equip/Tooling Operator Material Setup Other Process Supplier Training Unapproved					,						
			F/	AULI	T CATE	GORY					
Cen Cra Cru Cuf Hea Insp	shed/Crimped		General  Bend  BOM/Route  Broken/Damaged  Burrs  Contamination  Countersink  Cut Too Short  Drill Holes		Grain Hardware Inspection Incomplete Instructions Incomplete/Unclear Maintenance Mislabeled Misread			Ovalized Pressure/Forced Over/Under tolerance Temperature/Cure Part Incorrect Weld Part Lost/Missing Wrong Stock Pulled Part Moved Positioned Wrong Power Loss/Surge Other			

Out of Calibration

Out of Sequence

Outside Dimensions

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Turning Sequence

Wave/Twist in Tube

Torque Waves in Extrusion

Drawing

Finish Folio